MARION COUNTY SURVEYOR'S OFFICE

DEBRA S. JENKINS MARION COUNTY SURVEYOR

Method of Establishment: County:

Type of Marker: Boat spike w/washer over RR spike 6" down

Date: 7-30-09

Crew: Finney

Name: 150330B N: 495 451.248 (m) E: 50 917.203 (m)

Party Chief: Wilcoxen

SECTION CORNER RECORD SEC. 30 TWN. 15_{N} RNG. 3_{E}

5.

53.80'

BRYAN F. CATLIN, PLS TECHNICAL SUPERVISOR

Line of Hanna Ave 4000 S

Standish Dr.

(PwP) 1.

4. (PwP) 136.04'

Mooresville Rd 3700 S

134.21

3. PwP

Mann Rd 4500 W (PwP) 2.

A 1957 survey for Hal Howard by Ralph E. Schooley recorded in TLR 1666. Page 163 calls for a RR spike. 5/12/1999 Kiste found a RR spike down 7" under two layers of asphalt and set a boat spike w/washer at surface (MCSO Job #99-0014).10/1/2004 Wilcoxen called same.7/30/09 Wilcoxen called same.

REF.	DISTANCE	DESCRIPTION
1.	37.10'	Mag nail w/washer S PwP #62-657 A 8" up
2.	71.11'	Mag nail w/washer NW PwP #44-657 A 24" up
3.	134.21'	Mag nail w/washer N PwP #105-657 A 6.5' up
4.	136.04'	Mag nail w/washer S PwP #47-657 A 6.5' up
5.	53.80'	Top nut of fire hydrant

REFERENCE:

Hal Howard Survey TLR 1666 PG 163 1957 THIS CORNER POSITION REPRESENTS A "TITLE" CORNER AND MAY NOT NECESSARILY REPRESENT THE POSITION BASED ON RECORD CORNERS.